

3. Inch measurement assignment. With reference to Fig. 1-23 and using the scale:

1:1 decimal inch scale; measure distances A through F

1:1 fractional inch scale; measure distances G through M

1:2 decimal inch scale; measure distances N through T

1:2 fractional inch scale; measure distances U through Z

4. Foot and inch measurement assignment. With reference to Fig. 1-23 and using the scale:

$1'' = 1' - 0''$ , measure distances A through F

$3'' = 1' - 0''$ , measure distances G through M

$\frac{1}{4}'' = 1' - 0''$ , measure distances N through T

$\frac{3}{8}'' = 1' - 0''$ , measure distances U through Z




Fig. 1-23 Scale measurement assignment for Assignment 2 (on p. 16) and Assignments 3 and 4.