

Select one of the problems shown in 9-68
and make a two-view working drawing of the part. Use
partial sections when they will achieve clarity of drawing.




Fig. 9-68 Hold-down bracket.